


# Pressure Switch over (100% of fill)

→ Pressure in the cavity



→ The maximum pressure on the part is ~36 MPa.

→ Pressure in the system

