



## Filling pattern, isochrones & weld lines



→ This result presents the filling distribution.

### → Weld lines

→ The contour lines show the acceleration and deceleration of the material.



→ The red lines indicate possible weld lines on the part.